

EVENT DETAIL

LR/IHS/IMO Ship No.	9186041	Event ID	651146
Ship Name at time of Incident	MANTA		
Event Type	Ship Casualties	Detail	Hull / Machinery Damage
Event Group	Hull / Machinery Damage	Significance	Serious
Start Date	2005-12-20	End Date	2005-12-20
Total Loss	No	Pollution	No

Tug MANTA IMO No. 9186041 was involved in a hull/machinery incident at Willemstad, Netherlands Antilles on 20 Dec 2005

RELATED EVENTS

Relationship	Event ID	Event Type	Detail	Significance	Start Date	Ship Name
Parent to	651147	Ship Casualties	Hull / Machinery Damage	Serious	2005-12-20	MANTA
Parent to	651148	Ship Casualties	Hull / Machinery Damage	Serious	2005-12-20	MANTA

EVENT DETAILS

Tug MANTA IMO No. 9186041 was involved in a hull/machinery incident at Willemstad, Netherlands Antilles on 20 Dec 2005

CAPSIZED WHILST MANOEUVRING VESSEL IN TOW TO STERN AT WILLEMSTAD, CURACAO, NETHERLAND ANTILLES ON 20/12/05. SUBSEQUENTLY REPAIRED AND RETURNED TO SERVICE.

ASSISTED VESSEL PUT IT'S ENGINE IN REVERSE TO SLACKEN THE TOW AND VESSEL WAS RIGHTED. ENGINE ROOM AND ENGINE EXHAUSTS FLOODED. NO INJURIES OR POLLUTION REPORTED.

Significance	Serious	Component	WHOLE HULL/SHIP	Component Position	WHOLE
Detail	Hull / Machinery Damage	Load Status	Not applicable	Weather	Unknown/Not Reported
External Item	Wire, ropes	Total Loss	No	Pollution	No
Action	Capsized	Pollutant		Quantity	

LOCATION DETAILS

Context	Event	Start Environment	In Port/Harbour/Dock/at...	End Environment	In Port/Harbour/Dock/at...
Location	Willemstad	Town	Willemstad	Type	
Zone	West Indies	MarsdenGridReference	43	POSITION	12 06 00 N, 68 56 00 W

SHIP DETAILS AT TIME OF INCIDENT

Ship Name	MANTA	LR/IHS/IMO Ship No.	9186041	Flag	Netherlands Antilles
Registered Owner	Korsou Exploitatie	Country of Domicile	Curacao	Ship Status	IN SERVICE/COMMISSION
Detail Status	In	Official Number		GT	275

DWT	Attendance/Assisting 0	Ship Type	Tug	Built	2005
-----	---	-----------	------------	-------	-------------

Class: **Lloyds Register****VOYAGE DETAILS**

Origin	Unknown	Destination	Unknown
Removal Type	Proceeded For Repair		

CARGO DETAILS

© 2020 IHS Global Limited. IHS Global Limited assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has a contract with IHS Global Limited and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.