

Caught on Camera: Containership Takes Out Crane in Busan, South Korea


April 6, 2020 by Mike Schuler

A major accident was caught on camera today at the Port of Busan today when a containership struck multiple shoreside gantry cranes and another ship while berthing.

The video shows the Milano Bridge approaching its berth with the assistance of tugs at Busan New Port. In the video, you can one of the cranes collapse over the stern of the Milano Bridge. Another two cranes were also impacted along with a second ship, identified Seaspan Ganges.

No injuries were reported.

Check out the incident video below:



The incident was also captured from a second viewpoint in the video below (which appears to be sped up):

K Line megaboxship destroys crane at Pusan port in dramatic video



Related gCaptain Articles



The gCaptain Tool Pen



Scary Video Shows Giant Cranes Collapse in Small Dutch Canal -Incident Photos and Video



Click And Subscribe To gCaptain



Offloading Giant Cranes from a Ship -Here's How It's Done [VIDEO]

Powered by

Filed Under: Maritime News, News

Tagged With: containerships, incident video

SIGN UP FOR GCAPTAIN DAILY

Join the 58,849 smart Maritime Professionals who receive our daily newsletter.

Your email address

SIGN UP

FEATURED



U.S. Supreme Court Rules in Favor of Ship Owner in Athos I 'Safe Berth' Case



Navy Hospital Ship Joins Frontline of U.S. Coronavirus Battle



Seafarers on Maersk Ship Test Positive for COVID-19 in China



PHOTOS: USNS Comfort Arrives in New York Harbor



Wallenius Wilhelmsen Announces 2,500 Temporary Layoffs in U.S. and Mexico

VIDEO



VIDEO: THANK YOU To The Unseen Maritime Professionals On The Front Lines Of COVID-19



Watch: Heavy Seas Medevac in Bering Sea

Watch: Wild Docking in Norway

LATEST NEWS

Caught on Camera: Containership Takes Out Crane in Busan, South Korea

Coast Guard: 93,000 Crew Members Still Stuck on Cruise Ships Off United States

Golden Ray Salvage Continuing 'Day and Night'